



Release Notes

Product Name: KDS-8F

Current Version: Type

Туре	Number	Date
Firmware	3.5.2.0	October 2019
Software	_	_
Web	_	_
Hardware	_	_

RN Date: October 10, 2019

Reference: 14085

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
KDS-8F	N/A	N/A	N/A

Technical Notes:

- This is a release note for a new product.
- The following KDS-8F features are supported by Kramer Network version 2.2: Firmware upgrade, IP address configuration, Virtual Matrix and Video Wall setting.
- When using Kramer Network version 2.2 with KDS-8F devices, you may not use other models of KDS devices (KDS-EN/DEC5, KDS-EN/DEC6) in the same environment.
- To change the mode of operation between Genlock and Fast Switch or to configure the Multiview feature, <u>Blue River Agent Software</u> is required. The next version of Kramer Network will support these functions.

Codependency with Other Products and Software:

There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com
Web: www.kramerav.com





Release Notes

Product Name: KDS-8F

Current Version: Type

Туре	Number	Date
Firmware	3.5.2.0	October 2019
Software	_	_
Web	_	_
Hardware	_	_

RN Date: October 10, 2019

Reference: 14085

This is a release note for a new product. For a list of new product features see:

www.kramerav.com/manual/KDS-8F

Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
16085	Compressed Audio (Dolby/DTS) input is not supported – if compressed audio is presented in the input, the resulting output is audio noise.

Known Limitations (including compatibility limitations):

QC ID	Limitation Description
	None listed

Preceding Version: N/A



KRAMER ELECTRONICS, Ltd.

E-mail: <u>info@kramerav.com</u>
Web: <u>www.kramerav.com</u>